

# Fontana on Route 322

Yahoo! Maps, Driving Directions, and Traffic

Page 1 of 1



<http://maps.yahoo.com/index.php>

10/23/2008

**Fontana Parking:** Limited. Lighting poor. Drop-off difficult during peak times.

**Traffic Volume:** 15,000 cars per day.

**Accidents:** Comparable with Zion ECC.

## PA 934 @ Louser Road in 38

Date Range: 1/1/1998 to 12/31/2007 \*

USER\_ID/QUERY ID:  
dmarmosr\_0920091014017



Area of Interest: (In County 38 On State Route 934(P) Between Segment 0070 Offset 1655 and Segment 0080 Offset 200) or (In County 38 On State Route 0934(B) Between Segment 0071 Offset 1655 and Segment 0081 Offset 200)

CRASH SEVERITY LEVEL BY YEAR

	1999	2001	2005	2006	2007	ALL YEARS
	CRASHES	CRASHES	CRASHES	CRASHES	CRASHES	
MINOR INJURY CRASH	0	0	0	1	0	1
MODERATE INJURY CRASH	0	0	1	1	1	3
PROPERTY DMG ONLY CRASH	1	1	0	0	0	2
TOTAL	1	1	1	2	1	6

## CRASH DESCRIPTION TYPES BY YEAR

	1999	2001	2005	2006	2007	ALL YEARS
	CRASHES	CRASHES	CRASHES	CRASHES	CRASHES	
ANGLE	1	0	0	0	0	1
HIT FIXED OBJECT	0	0	0	1	0	1
REAR END	0	1	1	1	1	4
TOTAL	1	1	1	2	1	6

## PERSON INJURY SUMMARY BY YEAR

	1999	2001	2005	2006	2007	ALL YEARS
	PERSONS	PERSONS	PERSONS	PERSONS	PERSONS	
FATALITIES	0	0	0	0	0	0
MAJOR INJURIES	0	0	0	0	0	0
MODERATE INJURIES	0	0	2	1	2	5
MINOR INJURIES	0	0	0	1	0	1
UNKNOWN SEVERITY	0	0	0	0	0	0
UNKNOWN IF INJURED	0	0	0	0	0	0

\* PLEASE NOTE: Crash information for 2008 is incomplete at the time of this printing. As such, data for 2008 are not included in this report.

IMPORTANT: The information contained in this document is drawn from raw data and should not be interpreted as representing an engineering judgement or determination made by the Department of Transportation as to the type and severity of accidents noted herein.

Print Date: 10/14/2008

CDART - PUBLIC REQUEST / PRESS INQUIRY REPORT (01-07)